# STARLITE SPINTECH LIMITED PROJECT:- TULIP RESIDENTIAL APARTMENT & VILLAS PHASE-III, AT BALANAGAR, HYDERABAD.



# **MONTHLY PROGRESS REPORT NO- 10**

### HEAD OFFICE STARLITE SPINTECH LIMITED

601, 6thFloor, Shangrila Plaza No 14 Road No.2, BANJARA HILLS, HYDER

STARLITE SPINTECH LIMITED

#### PROJECT:- TULIP RESIDENTAIL APARTMENT PHASE-III AT BALANAGAR

#### **MONTHLY PROGRESS REPORT NO- 10**

S. No	Apartment	Facing	Build up Area in Sft	Plot Marking	4 <sup>th</sup> Floor Brick	4 <sup>th</sup> Floor Int. Plastering	5 <sup>th</sup> Floor Brick work	) 유 5	Pergola & O.T.Columns	Overhead Tank Slab	Pergola Desing	External Plastering	Bathrooms Water Profing	Tiles Work	Staicase Railing	Luppum work
1			4400	C	C	C	C	P	P	-	-	P	P	-	C	P

#### PROGRESS OF WORK: - TULIP PROJECT – BLOCK – "A"

#### **Progress Report since 01.08.2017 to 01.09.2017**

- > Staircase, Pergolas, Lift Columns Reinforcement overlapping work completed.
- > Staircase Pergolas and lift columns concrete work completed.
- ➤ Slab concrete work for Overhead tank purpose work completed.
- ➤ Lift Retaining wall concrete work completed.
- > 5<sup>th</sup> Floor Brick work completed.
- > 5<sup>th</sup> Floor Ceiling plastering work completed.
- ➤ 4<sup>th</sup> Floor Internal Plastering work completed.
- > 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> Floor water proofing and brick bat work completed.
- > 5<sup>th</sup> Floor Electrical wall chipping for Electrical Pipe laying work completed.
- $\succ$  5<sup>th</sup> Floor Electrical Pipe Laying and metal boxes fixing work completed.
- > 5<sup>th</sup> Floor Loft Slabs work completed.
- > 1<sup>st</sup>, 2<sup>nd</sup> Floor CPVC and PVC internal work completed.
- > 3<sup>rd</sup> and 4<sup>th</sup> Floor Wall chipping for plumbing purpose work completed.
- > 3<sup>rd</sup> and 4<sup>th</sup> Floor CPVC and PVC internal pipe laying work completed.
- > 3<sup>rd</sup> Floor Flat No.304 Concrete shelf work completed as per customer requirement.
- ➤ 4<sup>th</sup> Floor Internal Luppum 1<sup>st</sup> coat work completed.
- > M.S.Railing fixing work above staircase railing purpose work completed.
- > External Elevation brick work in progress.
- > 1<sup>st</sup> and 2<sup>nd</sup> floor Ledge wall work for Consoled tank purpose work completed.
- ➤ CPVC Pipe line Leakage checking work 1<sup>st</sup> and 2<sup>nd</sup> floor comleted.

# **Progress Report**

Overall Prog	ress Report in percentage	<u>Part – 01</u>
>	Excavation of Footing Pits	100%
>	Footings Concrete	100%
>	Gr.Floor Columns	100%
>	External Plinth Beam	100%
>	Internal Plinth Beam	100%
>	Grade Slab	100%
>	1 <sup>st</sup> floor Staircase	100%
>	1 <sup>st</sup> Slab Concrete	100%
>	2 <sup>nd</sup> Slab Columns	100%
>	2nd floor Staircase	100%
>	2 <sup>nd</sup> Floor Slab	100%
>	3 <sup>rd</sup> Slab Columns	100%
>	3 <sup>rd</sup> Floor Staircase	100%
>	3 <sup>rd</sup> Floor Slab	100%
>	4 <sup>th</sup> Floor Columns	100%
>	4 <sup>th</sup> Slab Staircase	100%
>	4 <sup>th</sup> Floor Slab	100%
>	5 <sup>th</sup> Floor Columns	100%
>	5 <sup>th</sup> Slab Staircase	100%
>	5 <sup>th</sup> Floor Slab	100%
>	6 <sup>th</sup> Floor Columns	100%
>	6 <sup>th</sup> Slab Staircase	100%
>	6 <sup>th</sup> Floor Slab	100%
>	Ground Floor Ceiling plastering	40.0%
>	First Floor Brick work	100%
>	Second Floor Brick work	100%
>	Third Floor Brick work	100%
>	Fourth Floor Brick work	100%

>	First Floor Wall cutting & Electrical Pipe conduct work completed	100%
>	Second Floor Wall cutting &Electrical Pipe conduct work completed	100%
>	Third Floor Wall cutting & Electrical Pipe conduct work completed	100%
>	First Floor Ceiling plastering work completed.	100%
>	Second Floor Ceiling plastering work completed.	100%
>	Third Floor Ceiling plastering work completed.	100%
>	First Floor Wall plastering work completed.	100%
>	Second Floor Wall plastering work completed.	100%
>	Third Floor Wall plastering work completed.	100%
>	Fourth Floor Wall plastering work completed.	100%
>	Fifth Floor Ceiling Plastering work completed.	100%
>	Fifth Floor Wall Plastering work in progress.	25.0%
>	1st Floor All Toilet wall cutting/CPVC & PVC Pipe work completed.	100%
>	2 <sup>nd</sup> Floor All Toilet wall cutting/CPVC & PVC Pipe work completed.	100%
>	3rd Floor All Toilet wall cutting/CPVC & PVC Pipe work completed.	100%
>	4 <sup>th</sup> Floor All Toilet wall cutting/CPVC & PVC Pipe work completed.	100%
>	1st & 2 <sup>nd</sup> Floor CPVC Pipe Line Leakage Checking work completed.	100%
>	1 <sup>st</sup> ,2 <sup>nd</sup> ,3 <sup>rd</sup> Floor Ladge Wall for Consoled Tank work completed.	100%
>	1st ,2 <sup>nd</sup> ,3 <sup>rd</sup> Floor Water Proofing work completed.	100%
>	1st, 2 <sup>nd</sup> ,3 <sup>rd</sup> Floor Brick Bat work completed.	100%
>	East side Elevation work in progress.	50.0%
>	West Side Elevation work in progress.	<b>75.0%</b>
>	North Side Elevation work in progress.	50.0%
>	South Side Elevation & Plastering work in progress.	80.0%
>	Staircase Head room Columns Concrete work Completed.	100%
>	Lift Room Columns Concrete work completed.	100%
>	Columns Concrete for Overhead tank Purpose work completed.	100%
>	Pergola Columns Concrete works in progress.	60.0%
>	M.S.Staircase Railing work above steps work completed.	100%

> 5<sup>TH</sup> Floor wall cutting & Electrical Pipe Conduct work in progress.

50.0%

## **WORK SITE PHOTOGRAPHS**



5<sup>TH</sup> FLOOR BRICK WORK





5<sup>TH</sup> FLOOR BRICK WORK





5<sup>TH</sup> FLOOR BRICK WORK





CHAIRMAN SIR SITE INSPECTION PERGOLA COLUMNS CONCRETE WORK







 $\frac{\text{CHAIRMAN SIR SITE INSPECTION OVERHEAD STAIRCASE COLUMNS CONCRETE}}{\text{WORK}}$ 








INTERNAL CPVC PIPE LINE LECKAGE CHECKING WORK





M.S. RAINING WORK ABOVE STAIRCASE WORK



STARLITE SPINTECH LIMITED

Prepare by Mohammed Airaj Ahmed



# <u>LUPPUM MIXING & LAYING WORK FOR FOURTH FLOOR INTERNAL PURPOSE.</u>



STARLITE SPINTECH LIMITED



Prepare by Mohammed Airaj Ahmed



EAST SIDE ELEVATION BRICK WORK



NORTH SIDE ELEVATION BRICK WORK



SOUTH SIDE ELEVATION BRICK WORK