# STARLITE SPINTECH LIMITED PROJECT :- TULIP RESIDENTIAL APARTMENT & VILLAS PHASE-III, AT BALANAGAR, HYDERABAD.



### **MONTHLY PROGRESS REPORT NO- 20**

## HEAD OFFICE STARLITE SPINTECH LIMITED

601, 6thFloor, Shangrila Plaza No 14 Road No.2, BANJARA HILLS, HYDEREABAD

STARLITE SPINTECH LIMITED

#### **INTERNAL EACH FLATS AS ON POSITION WORK:**

Flat No.101 :- Handover Flat to Customer

Flat No.102 :- Handover Flat to Customer

Flat No.104 :- Handover flat to customer.

Flat No.201 :- Handover flat to customer.

Flat No.202 :- Handover flat to customer.

Flat No.203 :- Handover flat to customer.

Flat No.204 :- Handover flat to customer.

Flat No.301 :- Handover flat to customer.

Flat No.302 :- Handover flat to customer.

Flat No.303 :- Handover flat to customer.

Flat No.304 :- Handover flat to customer.

Flat No.401 :- Handover flat to customer.

Flat No.403 :- Handover flat to customer.

Flat No.404 :- Handover flat to customer.

Flat No.502 :- Handover flat to customer.

Flat No.503 :- Handover flat to customer

#### PENDING WORK FOR THIS FLAT BECAUSE OF CUSTOMER WORK IN PROGRESS.

Flat No.103 :- Only one Doors Frames with Door fixing work. & Doors Frames Polish work.

Flat No.402 :- Final Coat Paint & Doors Frames Polish work & Plumbing Final fitting work.

Flat No.501 :- Plumbing final fitting Final Paint & Doors Frames Polish.

Flat No.504 :- Plumbing & Electrical Final Fitting work.

# PROJECT :- TULIP RESIDENTAIL APARTMENT PHASE-III AT BALANAGAR MONTHLY PROGRESS REPORT NO- 20

S. No	rt.	Facing	Build up Area in Sft	Plot Marking	Pits Excavation	P.C.C.	Columns marking	Footings concrete	Pedestal	Ext.Plinth Beam	Internal Plinth Beam	Still's Floor Columns Concrete		1st Floor Slab	1st Floor Columns Concrete	Stills Floor Slab De- shuttering work
1			4400	C	C	C	C	C	C	C	C	C	C	C	C	P

#### PROGRESS OF WORK: - TULIP PROJECT – BLOCK – "B"

- Progress Report since 01.08.2018 to 01.10.2018
- Footings work completed
- ➤ Pedestal Columns work completed.
- ➤ P.C.C. below Plinth Beam work completed.
- External & Internal Plinth Beam Reinforcement laying and shuttering work completed.
- External & Internal Plinth Beam Concrete work completed.
- > Still's Floor Columns overlapping work completed.
- ➤ Soil Back filling and soil compaction work completed for grade slab purpose.
- > Grade Slab Reinforcement and concrete work completed.
- > Still's Floor Columns Starter marking and concrete work completed.
- Still's Floor Columns shuttering and concrete work completed.
- > Still's Floor Staircase Reinforcement/Shuttering and concrete work completed.
- Still's Floor shuttering & bar bending work completed.
- Still's Floor Slab Concrete work completed.
- ➤ 1st Floor columns starter marking and concrete work completed.
- ➤ 1<sup>st</sup> Floor columns concrete work completed.


- ➤ 1<sup>st</sup> Floor Slab Shuttering and bar bending work completed.
- ➤ 1<sup>st</sup> Floor Slab concrete work completed.
- > 2<sup>nd</sup> Floor columns Reinforcement overlapping and shuttering work completed.
- ≥ 2<sup>nd</sup> Floor columns concrete work completed.
- ➤ 2nd Floor Slab shuttering work completed.
- > 3<sup>rd</sup> Floor columns Reinforcement overlapping and shuttering work completed.
- ➤ 3<sup>rd</sup> Floor columns concrete work completed
- ➤ All Flats 1<sup>st</sup> Floor Brick work completed.
- ➤ All Flats 2<sup>nd</sup> Floor Brick work completed work completed.
- > 3<sup>rd</sup> Floor Brick work in progress.
- ➤ All Flats First Floor Electrical Pipe Conduct and Metal boxes fixing work completed.
- First Floor Flat No.101 & 104 plastering work completed.
- ➤ 2nd Floor All Flat ceiling plastering work completed.
- ► 4<sup>th</sup> Floor Slab Shuttering and bar bending work completed.
- ➤ 4<sup>th</sup> Floor Slab Concrete work completed.
- ➤ 5th Floor Columns starter marking and concrete work completed.
- ➤ 5th Floor Columns Steel overlapping work completed.
- ➤ 5<sup>th</sup> Floor Columns concrete work completed.
- > 5th Floor Slab shuttering work in progress.
- > 5th Floor Slab steel cutting work in progress.
- ➤ 2<sup>nd</sup> Floor Flat No.201 & 203 Plastering work completed.

 $\triangleright$ 

# <u>TULIP – B :-</u>

OVERALL PROGRESS REPORT IN PERCENTAGE	WORK %
R.C.C WORK	
Still's Floor Slab Concrete work completed.	100%
First Floor Slab Concrete work completed.	100%
Second Floor Slab Concrete work completed.	100%
Third Floor Slab Concrete work completed.	100%
Fourth Floor Slab Concrete work completed.	100%
BRICK WORK:-	
First Floor All Flat Brick work completed.	100%
Second Floor All Flat Brick work completed.	100%
Third Floor All Flat Brick work in progress.	95%
INTERNAL PLASTERING:-	

First Floor Flat No.101 & 104 plastering work completed.	100%
First Floor Flat No.102 & 103 Plastering not yet start.	0.0%
Second Floor Flat No.201/202 & 203 plastering work completed.	100%
Second Floor Flat No.204 Plastering work in progress.	50%



 $\underline{\mathbf{4^{TH}\,FLOOR\,SLAB\,SHUTTERING\,WORK}}$ 





4<sup>TH</sup> FLOOR SLAB BAR BENDING WORK CUM ELECTRICAL WORK



STARLITE SPINTECH LIMITED

Prepare by Mohammed Airaj Ahmed



4<sup>TH</sup> FLOOR SLAB BAR BENDING WORK CUM ELECTRICAL WORK





**4<sup>TH</sup> FLOOR SLAB CONCRETE WORK** 



STARLITE SPINTECH LIMITED

Prepare by Mohammed Airaj Ahmed



**4<sup>TH</sup> FLOOR SLAB CONCRETE WORK** 



STARLITE SPINTECH LIMITED

Prepare by Mohammed Airaj Ahmed



**4<sup>TH</sup> FLOOR SLAB CONCRETE WORK** 






 $\underline{\mathbf{4^{TH}\,FLOOR\,SLAB\,CONCRETE\,WORK}}$ 



STARLITE SPINTECH LIMITED

Prepare by Mohammed Airaj Ahmed





**INTERNAL PLASTERING WORK** 



Prepare by Mohammed Airaj Ahmed



**INTERNAL PLASTERING WORK** 



Prepare by Mohammed Airaj Ahmed



**BRICK WORK IN PROGRESS** 



